

Adams Township, MI

Requisition No.

ENGINEER'S OFFICE

F. P. No. 1593

Drawn by H. T. Menden

TRIMOUNTAIN MINING CO.



TRIMOUNTAIN, MICH.

Checked by "

Date Dec 22 1911

SUBJECT Clearance at Head Sheave & Position of Skip at Plat

Shaft	A	B	C
No. 2	4'-4"	5'-6"	
3	4'-9"	8'-9"	
4	5'-0"	1'-6"	
B			{ 9"-16" empty 13"-24" full Large Skip
C			
D			
E			{ 10"-25" empty 14"-29" full Large Skip



Adams Township, MI

Requisition No.

ENGINEER'S OFFICE

F. P. No. 1593-B

Drawn by *[Signature]*

TRIMOUNTAIN MINING CO.





Checked by

TRIMOUNTAIN, MICH.

Date Dec 22 1911

SUBJECT *Distances Bail To sheave Along Rope When Skip is in Dump also sketches of sheave supports.*

shaft	A	B	
2	9'-10"	4'-4"	4 Ton Skips
3	13-6	4'-9"	" " "
4	6'-6"	5'-0"	6 Ton Skips.



Adams Township, MI

Requisition No.

ENGINEER'S OFFICE

F. P. No. 1593

Drawn by H. T. Mercer.

TRIMOUNTAIN MINING CO.

Checked by "

TRIMOUNTAIN, MICH.

Date Dec 22 1911

SUBJECT Clearance at Head Sheave & Position of Skip at Plat

Shaft	A	B	C
No. 2	4'-4"	5'-6"	
3	4'-9"	8'-9"	
4	5'-0"	1'-6"	Large Skip
B	5'-3"	3'-9"	9"-16" empty Large Skip
C	5'-3"	6'-6"	13"-24" full
D	5'-3"	6'-7"	
E	5'-3"	3'-9"	10-25 14-29 Large Skip

