

CHAMPION COPPER COMPANY

Adams Township, MI


SHOP SKETCH

Subject: Over Wind Poor Rock Dump

Date: Feb. 11-1915

6 Ton Skip

Scale  $\frac{3}{4}'' = 1'-0''$




F.P. 1683 A

Made by *JA.*

RETURN THIS SHEET TO SHOP FOREMAN WHEN WORK IS COMPLETED


Adams Township, MI



OVER WIND POOR ROCK DUMP  
3 TON SKIP  
Scale  $\frac{3}{4}$ " = 1'-0"

F.P. 1683-B

J.A.



1/2" x 3" Strap #1 All Holes 1/8" From Edge Make 2 Rand L.

3/4" x 4" Strap #2 All Holes 13/16" Countersunk 2" From Edge If Not Marked Make 2 Rand L.

4 R. 3/8" Plate Make  
 2 Plain #1 Make  
 2 Countersunk And  
 Turned #2 Rand L.  
 Drill Holes For Hinge 13/16"  
 All Others 7/16"

4 R. 1/2" x 4" x 4" x 24" Angles  
 1 Under Top Strap Drill 1/2" Countersunk  
 1 Under Bottom Strap On Each Dump Stringer

**UNDERGROUND  
 POOR ROCK DUMP 6 TON SKIP**  
 Scale 1/2" = 1'-0" Feb. 10 - 1915  
 J.A.

Note. See Print #1 For Curve  
 See Print #2 For Stringers

**PRINT # 3**

