

FEDERAL ENERGY REGULATORY COMMISSION
Office of Energy Projects
Division of Dam Safety and Inspections - Chicago Regional Office
230 South Dearborn Street, Suite 3130
Chicago, Illinois 60604
(312) 596-4430 Office - (312) 596-4460 Facsimile

In reply, refer to: P-10856

October 14, 2016

Mr. Jason Kreuzscher
Vice President, Operations
Renewable World Energies, LLC
100 State Street, P.O. Box 264
Neshkoro, WI 54960

Re: Follow-up to the 2016 Dam Safety Inspection – Completed Items
Au Train Hydroelectric Project (FERC No. 10856)

Dear Mr. Kreuzscher:

We have completed our review of your September 28, 2016 letter regarding the removal of Iron Oxide from the embankment drains at your Au Train Hydroelectric Project (P-10856). The letter indicated that only iron oxide was found and removed from the toe drain system. This submittal completes all the items/tasks identified during the 2016 dam safety inspection.

If you have any questions, you may contact Mr. Chapman at 312.596.4446 or at peter.chapman@ferc.gov or me at 312.596.4430.

Sincerely,

John A. Zygaj, P.E.
Regional Engineer

Document Content(s)

10856_2016 DSI Insp Followup Ltr_completed_37894.PDF.....1-1