

Record of Engineers and Firemen

William McCormick

Fireman, August 1872

Engineer, September 1873

October 28, 1887 - Ran off open switch at L'Anse.

January 4, 1888 - Backed into train in Marquette yard, injured baggage car and engine tender. Suspended one week.

March 13, 1889 - Was on engine 103. Fireman handled and collided with engine no. 116, F. Daly, hostler, in Marquette yard. Suspended 15 days.

December 4, 1893 - Left here with train No. 7, engine no. 103. When he got to Eagle Mills discovered small crack in extension and delayed train by waiting there for another engine to come from Marquette. He should have gone along with engine no. 103, as crack in no way crippled her. Suspended 10 days.