

Record of Engineers and Firemen

William H. Greene

Fireman, 1866

Engineer, 1871

June 24, 1891 - Ran into tail end of ore train at West Switch, Marquette yard with train no. 4, wrecking cabooses and several ore cars, also damaging front end of engine no. 116. Wreck was caused by running too fast and not having train under proper control. Suspended till July 22, 1892.