

Photographs of May 2003 Dead River flood event damage.

5/19/2003



All that is left of the bridge over the Dead River at CR AAO.

5/19/2003



Remnants of the former bridge over the Dead River at CR AAO.



Flood damage at the former bridge over the Dead River at CR AAO.



CR AAT washed out at Mulligan Creek crossing.



Large scour area along the Dead River washed out CR AAT just upstream of the Mulligan Creek bridge crossing. Next photograph is a view from the top of the bluff, which is the former location of CR AAT.



View from the top of the bluff seen in the previous photograph showing the large bank that was washed out in the 2003 Dead River flood event and what is left of CR AAT on the left of the photograph.