Facility/Project Name City of Marquette - Former Cliffs Dow Site Address/Location				Driller/Drill Rig Rob / Enviro-Dynamics / Geo-Probe		Boring Number UPG-100CR / SB-16		
				Wright St & Lakeshore Blvd, Marquette, MI				DDM
Site Owner (If different than above.)				Project Number	Groundwater Depth	Comme	nts	
				99-059	~6 feet	Blind dr	ill to 4	0 feet
				Start Date	Well Name	Shown o	n draw	ving as SB-16
				10/19/2009	UPG-100CR			
				Completion Date	Grid Location			
				10/19/2009			1	
TRIMEDIA SAMPLE	LENGTH	BLOW	DEPTH			USCS	PID	REMARKS
NUMBER	RECOVERED	COUNT						
			0	0-18" POORLY GRADED SAND Fine grained sand, non-plastic, wet, dark brown.		SP		
			-					
			-					
	18"		-					
			1					
			-					
			-					
			-					
			2		0-16" WELL GRADED SAND Sandy clay material, wet, reddish brown.			Collected sample
			-	Sandy clay material, wet,				
			-					
			-					
	16"		3					
			-					
			-					
			-					
			4	_				
			-					
			-					
			-					
			-					
			5					
			-					
			-					
			-					
			6					
			-					
			-					
			-					
			7					
			-					
			-					
			-					
			8	Blind drill				
			-					
			-					
			-					
			9					
			-					
			-					
			-					
			- 10					
			-					
			-					
			-					
			-	0.440.77	CAND	a		
			11	0-14" WELL GRADED Sandy clay material, wet,	SAND reddish brown.	SW		Collected sample
			-	and the state of t				
			-					
			-					
			12	14-19" POORLY GRAD	DED SAND	SP		
			-	Silty sand, wet, black.				
			-					
			13	EOB				
	DDM	Geologist/Task					1	TriMedia
DDM Geologist/Technician TAG Reviewed				Page 1 of 1				Consultants